

Software Release Notes

Software DVB part: 2.57.0.1-2594d
Signature: Jan 24 2014, 09:52:41
Software TV part: n/a
Signature: n/a

Intended for the following product: Digit ISIO C MS2 Aprico2

For a complete list of all products please consult the ProductInformationSystem.
(<https://pis.technisat-digital.de:42063>)

Highlights:

Service release 6 update Aprico Phase 1 for Digit ISIO C

- Online product registration
- Shop mode
- ISIO list for factor settings V40

Fixed Mantis Bugs:

ID 26645, Digit ISIO C MS2 Aprico2, P1 : "[IP Daun]Produktregistrierung (Schritt 1): Seriennummer nicht gefunden"

Status : resolved 2.57.0.1-2594d, Reproducibility : always

Hauptmenü, Einstellungen, Sonderfunktionen, Produktregistrierung (Schritt 1):
Seriennummer wird nicht gefunden, Felder für Produktbezeichnung und Seriennummer können nicht angewählt und verändert werden, die Seriennummer ist als Pflichtfeld durch ein "Stern" markiert und muß ausgefüllt werden, die eingebendete Fehlermeldung: "Seriennummmer nicht gefunden (0008c92178400183). Abfrage fehlgeschlagen. Beachten sie weitere Fehlermeldungen." ist für den Kunden irreführend, weil die Seriennummer, wie in der Systemkonfiguration als Hexadezimal Zahl in der Fehlermeldung enthalten ist, und die Fehlermeldung in diesem Fall, ein Überschreiten der Garantiezeit (am 25.05.2013 abgelaufen) anzeigen sollte.
Ein "Hilfstext Menü" wird nicht angeboten.
In der Fehlermeldung ist desweiteren ein Rechtschreibfehler enthalten, "Sie" sollte groß geschrieben werden.

ID 26644, Digit ISIO C MS2 Aprico2, P2 : "[IP Daun] Product registration does ignore country setting"

Status : resolved 2.57.0.1-2594d, Reproducibility : always

In AutoInstall the product registration does ignore the made country setting for e.g. although the user has accepted "Deutschland" as country the product registration does insert in the formular "Belgien" so the user must again set up "Germany".

ID 26646, Digit ISIO C MS2 Aprico2, P2 : "[IP Daun] Produktregistrierung aufrufen: Blaues Bild ohne Inhalt"

Status : resolved 2.57.0.1-2594d, Reproducibility : several times

Produktregistrierung aufrufen: Blaues Bild (einheitlich gefärbt) ohne Inhalt erscheint, im Frontdisplay steht "Produktregistri...", Ton des zuletzt gewählten TV Programms ist zu hören, mit Menütaste kann zurück zum TV-Bild geschaltet werden.

ID 26948, Digit ISIO C MS2 Aprico2, P1 : "keine Wiedergabe vom Maxdome Kauf-oder Leihfilm"

Status : resolved 2.57.0.1-2594d, Reproducibility : several times

Zeitweise ist keine Wiedergabe von Maxdome Kauf-oder Leihfilmen möglich. Der Bandbreitencheck ist erfolgreich, der Film versucht dann auch mehrfach zu starten. Während diesen Versuchen wird das Maxdome Bedienfeld mit Fortschrittsbalken immer wieder ein- bzw. ausgeblendet. Nach 3 Versuchen erscheint die Meldung "Seite nicht verfügbar" (siehe Screenshot, siehe Video). Die Wiedergabe von Trailern funktioniert hingegen ohne Probleme.

Nach einer Netztrennung des Gerätes oder nach der Trennung des LAN-Kabels laufen diese Filme wieder.

Fehler konnte mehrfach an meinem Testbox beobachtet werden und es liegen gleichlautende Kundenreklamationen im Service Center vor.

ID 26991, Digit ISIO C MS2 Aprico2, P2 : "Maxdome movie playback does not always start from beginning"

Status : resolved 2.57.0.1-2594d, Reproducibility : often

- The movie playback on maxdome often does not start from beginning
- Reported by M.Schweden - wireshark sniff when that issue occurred is attached (IP DIGIT ISIO S: 192.168.130.143)

ID 27179, Digit ISIO C MS2 Aprico2, P1 : ""Perfect" Recording nimmt Sendung nicht auf"

Status : resolved 2.57.0.1-2594d, Reproducibility : several times

"Perfect" Recording ist aktiviert und es ist eine Aufnahmebereitschaft von 30 Minuten eingestellt. Es werden nun auf einem ÖR Sender 2 aufeinanderfolgende Events als Timer Aufnahmen programmiert.

Der erste Event wird vollständig aufgenommen, der zweite direkt anschließende Event wird jedoch nur als Datei angelegt, deren Aufnahmedauer lediglich 1-2 Sekunden beträgt.

Auch ein drittes Event wurde mit 2 Sekunden aufgenommen.

ID 27192, Digit ISIO C MS2 Aprico2, P2 : "Hinweis auf HD-Plus"

Status : resolved 2.57.0.1-2594d, Reproducibility : always

Der Hinweis auf eine Seite www.hd-plus.de macht in der Schweiz oder in Österreich keinen Sinn. Dieser Hinweis sollte verallgemeinert werden, oder ganz entfernt werden

ID 27210, Digit ISIO C MS2 Aprico2, P2 : "Continuous PIN dialog when starting any DVR playback on live channel with PIN protected event"

Status : resolved 2.57.0.1-2594d, Reproducibility : always

- Switch to channel with FSK event which could be descrambled by side of a CI module (and therefore would lead to user PIN request dialog)
- Start any DVR playback (NAV -> Own Records) in fullscreen mode
- The PIN request dialog (from previous live service) is continuously shown

ID 26448, Digit ISIO C MS2 Aprico2, P2 : "Broadcast info (SI) at Kabel Kiosk channels -> Special characters faulty."

Status : closed 2.57.0.1-2594c, Reproducibility : always

Broadcast info (SI) at Kabel Kiosk channels -> Special characters faulty.

ID 26927, Digit ISIO C MS2 Aprico2, P1 : "[KabelKiosk]: If there is an active recording in background, all parental ratet services are unblocked"

Status : closed 2.57.0.1-2594c, Reproducibility : always

[KabelKiosk]: If there is an active recording in background, all parental ratet services are unblocked

ID 26958, Digit ISIO C MS2 Aprico2, P2 : "Wrong error message after entering not existing url"

Status : closed 2.57.0.1-2594c, Reproducibility : always

Wrong error message after entering not existing url.

- Enter not existing url

--> Message "Network problem. The network connection of your device is not workingcorrectly..." appears, but right is a message about not found website/server.

ID 26961, Digit ISIO C MS2 Aprico2, P2 : "Keine Dekodierung von Sky Sender nach PIN Eingabe"

Status : closed 2.57.0.1-2594c, Reproducibility : always

Es ist eine HD+ Karte gesteckt und ein Sky CI+ Modul mit V13 Karte. Nun schaltet man auf einen HD+ Sender, wartet kurz und schaltet dann auf einen Sky Sender, der eine PIN Aufforderung einblendet. Man gibt nun die korrekte PIN ein. Die PIN Aufforderung wird ausgeblendet und der Bildschirm wird schwarz, die Audio/Video Dekodierung startet nun nicht.

Erst nach Programmumschaltung auf einen anderen Sender und zurück, wird der PIN gesperrte Sender wiedergegeben.

In einigen Fällen startet dies allerdings auch nicht die Wiedergabe, denn es wird hin und wieder stattdessen die Fehlermeldung eingeblendet "Dieser Sender kann mit einer HD+ Karte nicht empfangen werden. (Hinweis 144)"

ID 27199, Digit ISIO C MS2 Aprico2, P2 : "Empty message box when using TechniCrypt module with non paired smartcard"

Status : resolved 2.57.0.1-2594c, Reproducibility : always

Reported by T.Proksch (mail from 2013-10-12)

"Wird eine STB in Verwendung mit einem TechniCrypt genutzt, in welcher eine nicht mit diesem Modul gepairte SMC eingesteckt ist, dann ist die Meldung "Kein Zugriff 8" nur ganz kurz zusehen bevor diese mit folgender Meldung überblendet wird"

ID 26350, Digit ISIO C MS2 Aprico2, P1 : "HD+ card with CI+ module: Error message while zapping between HD+ channels"

Status : closed 2.57.0.1-2594b, Reproducibility : often

HD+ card with CI+ module: Error message while zapping between HD+ channels, "Kein Zugriff - Hinweis 8"

ID 26424, Digit ISIO C MS2 Aprico2, P2 : "Missing translation"

Status : closed 2.57.0.1-2594b, Reproducibility : always

Start direct recording with the REC button. Now press the REC button again. A dialogue with several options for the recording end time is shown but it is only partly translated.

"(to xx:xx)" should be for e.g. in german "(bis xx:xx)"

ID 26487, Digit ISIO C MS2 Aprico2, P1 : "Kein Live Streaming von Pay TV Sender"

Status : closed 2.57.0.1-2594b, Reproducibility : always

Pay TV Sender wie Sky sind nicht mehr über das UPnP Live Streaming verfügbar.

ID 26655, Digit ISIO C MS2 Aprico2, P1 : "Ordner konnten auf TSD formatierter Festplatte nicht erstellt werden"

Status : closed 2.57.0.1-2594b, Reproducibility : always

Ordner konnten auf TSD formatierter Festplatte nicht erstellt werden (Menü Filme verwalten, neuer Ordner), sie waren nur im Filme verwalten Menü sichtbar.

Nach kopieren von Ordnern oder Filmdateien von USB-Stick (Fat32 formatiert) auf TSD formatierte Festplatte waren Dateien/Ordner nur im Menü Filme verwalten sichtbar, beim Öffnen über die Navigatortaste (NAV Menü - Filme/DVR) werden auf der Festplatte weder Ordner noch die Filmdateien angezeigt.

ID 26694, Digit ISIO C MS2 Aprico2, P- : "Kein UPnP Streaming von eigenen Aufnahmen"

Status : closed 2.57.0.1-2594b, Reproducibility : always

UPnP Streaming von eigenen Aufnahmen auf PC, Android oder iOS Geräte startet nicht.

ID 26844, Digit ISIO C MS2 Aprico2, P2 : "[Haehnlein SW] Upnp server should allow access onto the meta file for a dvr recording"

Status : under test 2.57.0.1-2594b, Reproducibility : always

- Request by side of Haehnlein SW

- Upnp server should allow access onto the meta file for a dvr recording

ID 26914, Digit ISIO C MS2 Aprico2, P- : "HbbTV: SAt.1, ProSieben, kabel eins, SD/HD-Varianten: Steuerfunktion in "BMW-Werbe Menüpunkt" fehlerhaft. "

Status : closed 2.57.0.1-2594b, Reproducibility : always

HbbTV: SAt.1, ProSieben, kabel eins, SD/HD-Varianten: Steuerfunktion in "BMW-Werbe Menüpunkt" fehlerhaft.

ID 26422, Digit ISIO C MS2 Aprico2, P2 : "Playback of TS4-file without sound"

Status : closed 2.57.0.1-2594, Reproducibility : always

Playback of TS4-file without sound, the same file importet in "My TV Recordings" has sound.

ID 26425, Digit ISIO C MS2 Aprico2, P1 : "The STB rebooted if the second Conax smart card is inserted."

Status : closed 2.57.0.1-2594, Reproducibility : always

One Conax smart card is inserted in embedded slot. The second smart card is inserted in the second embedded slot. The STB reboots.

ID 26426, Digit ISIO C MS2 Aprico2, P1 : "SFI channel not present, no download over IP, no download over "arte""

Status : closed 2.57.0.1-2594, Reproducibility : always

SFI channel not present, no download over IP
Internet connection is "OK", no download over "arte"

ID 26491, Digit ISIO C MS2 Aprico2, P1 : "Stop der Video Wiedergabe"

Status : closed 2.57.0.1-2594, Reproducibility : always

Man schaltet auf einen verschlüsselten Sender, der entweder über das embedded CA System oder per CI Modul dekodiert wird. Nun öffnet man den Musik Modus und spielt einen Titel oder eine Playlist an. Anschließend verläßt man den Musikmodus mit der "TV/Radio" Taste. Die Audio Wiedergabe des aktuell eingestellten Sender startet, aber die Video Wiedergabe startet nicht.

Im Radio Modus äußert sich der Fehler ähnlich, daß statt dem Radio Hintergrundbild ein schwarzer Bildschirm gezeigt wird.

Dies kann vereinzelt auch auf FTA Sender auftreten, allerdings ist die Häufigkeit hier wesentlich geringer, daß die Video Wiedergabe nicht startet.

ID 26494, Digit ISIO C MS2 Aprico2, P1 : "Crash beim Zustecken eines CI-CAM"

Status : closed 2.57.0.1-2594, Reproducibility : always

- Irdeto CI+ CAM mit ORF-Karte einstecken und ORF-Programm entschlüsseln
- Zweites CI-CAM (z.B. Alphacrypt) in den zweiten Slot stecken und warten ... Crash ODER
- Irdeto CI+ CAM mit ORF-Karte einstecken auf z.B. ARD
- Zweites CI-CAM (z.B. Alphacrypt) in den zweiten Slot stecken und Init. abwarten
- Auf ORF-Programm umschalten Crash

ID 26501, Digit ISIO C MS2 Aprico2, P1 : "Geändertes PIN Handling bei Jugendschutz Aktivierung"

Status : closed 2.57.0.1-2594, Reproducibility : always

Das PIN Handling bei der Jugendschutz Aktivierung wurde dahingehend geändert, daß es nicht mehr notwendig ist, die bereits voreingestellte Geräte PIN einzugeben. Somit es es jedermann auch ohne Kenntnis der voreingestellten Geräte PIN möglich, das Gerät zu sperren. #26458

ID 26400, Digit ISIO C MS2 Aprico2, P- : "[Haenlein SW] No playback of imported recordings created by DVR Studio HD3 after copy to folder own recordings on another volume"

Status : closed 2.57.0.1-2586, Reproducibility : always

- Import a recording which was created with Haenlein DVR Studio HD3 to folder own recordings- Imported recording could be played back- Copy this recording to folder own recordings on another volume- After copy finished try to playback the copied record- It is not possible

ID 11294, Digit ISIO C MS2 Aprico2, P2 : "Video playback in www mode. The icon for play, stop and etc. should be shown in the form display."

Status : closed 2.57.0.1-2573, Reproducibility : always

Start video playback in www mode. For example "arte live web" at ARTE HD. Change to full screen and pause the playback. In this case the icon pause should be shown in the form display.(The behavior like in DVR playback mode)

ID 13753, Digit ISIO C MS2 Aprico2, P2 : "Open source licence hint probably incomplete"

Status : closed 2.57.0.1-2573, Reproducibility : always

The open source licence hint is probably incomplete since in comparison to MultyVision ISIO several packages for e.g. "busybox" are not listed.

ID 15794, Digit ISIO C MS2 Aprico2, P2 : "network activity during Standby quickstart modus"

Status : feedback 2.57.0.1-2573, Reproducibility : always

weather-app need about 40kb/hour. every 10 minutes there is a traffic from about 7kb.

If there is a costumer which has a volume rate he don't want to loose ~30MB per month for actualization during standby

ID 20912, Digit ISIO C MS2 Aprico2, P2 : "AI > network check <20% > not possible to abort/skip"

Status : closed 2.57.0.1-2573, Reproducibility : always

Not possible to abort/skip (info btn) network check within AI until 20% where reached.

ID 20913, Digit ISIO C MS2 Aprico2, P2 : "New ISIO list > later > to long duration until usable"

Status : closed 2.57.0.1-2573, Reproducibility : always

Message about new ISIO list after switch on > choose "later" > it needs an extremly long duration (1-2min) until "please wait" disappears and the device is usable.

ID 20914, Digit ISIO C MS2 Aprico2, P2 : "Menu ISIO list update > back btn > too long duration to leave menu"

Status : closed 2.57.0.1-2573, Reproducibility : always

Call menu ISIO list update and leave it directly by back btn. It needs an extremely long duration (~45sec) until "please wait" disappears and the device is usable. It is much faster to wait until the device has found the new list and leave the menu with back btn.

ID 22390, Digit ISIO C MS2 Aprico2, P2 : "Recods stops for a very short moment."

Status : closed 2.57.0.1-2573, Reproducibility : several times

During a record (timeshift live position), it can be, that the playback stops for a very short moment. playing this part again, no stop visible.

ID 22413, Digit ISIO C MS2 Aprico2, P2 : "arte HD HBBTV no video playback"

Status : closed 2.57.0.1-2573, Reproducibility : always

Switch to "arte HD" and open the HBBTV content with the RED button. Choose the page "ARTE +7" with the YELLOW button and select a video for e.g. "WILDE TIERE, GROßE LIEBE". Video playback will not start and audio playback is very choppy or also not available.

ID 25198, Digit ISIO C MS2 Aprico2, P2 : "Wrong display"

Status : closed 2.57.0.1-2573, Reproducibility : always

Not occupied channels are shown in SFI List (see attached pfd)

ID 25279, Digit ISIO C MS2 Aprico2, P2 : "channel numbering is not the same like at FAV list"

Status : closed 2.57.0.1-2573, Reproducibility : always

Watchmi channels are available at FAV list between other TV channels. Create a new "wake up timer" and choose the last channel. Channel numbers are continuously without the watchmi channels. So the channel numbering is not the same like at FAV list.

ID 25370, Digit ISIO C MS2 Aprico2, P2 : "App missing"

Status : closed 2.57.0.1-2573, Reproducibility : always

Call factory reset and install STB without network connection. Open app bar and select first app. The app will open and inform about the missing network connection. Now go back to app bar and the app will not be listed anymore instead a black empty space is shown.

ID 25371, Digit ISIO C MS2 Aprico2, P2 : "App bar default value should be "off""

Status : closed 2.57.0.1-2573, Reproducibility : always

After factory reset or AutoInstall the default value for the app bar setting should be "off".

ID 25600, Digit ISIO C MS2 Aprico2, P2 : "Language German: Help webbrowser: last menu point not translated"

Status : closed 2.57.0.1-2573, Reproducibility : always

Language German: Help webbrowser: last menu point not translated (option screen off)

ID 25607, Digit ISIO C MS2 Aprico2, P2 : "Defect in software update source modify: cancel an agreement but the entry was taken over"

Status : closed 2.57.0.1-2573, Reproducibility : always

Defect in software update source modify: cancel an agreement but the entry was taken over

ID 25662, Digit ISIO C MS2 Aprico2, P3 : ""ZOOM" button active in radio mode"

Status : closed 2.57.0.1-2573, Reproducibility : always

The "ZOOM" button is active in radio mode and settings can be changed. Since no life video can be seen this is unnecessary and the "ZOOM" button should be inactive in radio just like for e.g. the "PIP" button. #0011430

Already released versions:

Release	Build number	Date of SW	Comment
---------	--------------	------------	---------