

# Software Release Notes

Software DVB part: 2.57.0.1-2595d  
Signature: Jan 24 2014, 11:04:40  
Software TV part: n/a  
Signature: n/a

Intended for the following product: DigiCorder ISIO C MS2 Aprico2

For a complete list of all products please consult the ProductInformationSystem.  
(<https://pis.technisat-digital.de:42063>)

## Highlights:

Service release 5 update Aprico Phase 1 for DigiCorder ISIO C

- Online product registration
- Shop mode
- ISIO list for factor settings V40

## Fixed Mantis Bugs:

### **ID 25592, DigiCorder ISIO C MS2 Aprico2, P2 : "Crash during file copy"**

Status : resolved 2.57.0.1-2595d, Reproducibility : several times

A very large movie file (~31GB) has been copied from an external 3.5" USB HDD with own power supply to the internal harddisk. Several times it could be observed that the STB did crash and reboot at different copy progress stages.

### **ID 26729, DigiCorder ISIO C MS2 Aprico2, P2 : "[IP Daun] Produktregistrierung aufrufen: Blaues Bild ohne Inhalt"**

Status : resolved 2.57.0.1-2595d, Reproducibility : several times

Produktregistrierung aufrufen: Blaues Bild (einheitlich gefärbt) ohne Inhalt erscheint, im Frontdisplay steht "Produktregistri...", Ton des zuletzt gewählten TV Programms ist zu hören, mit Menütaste kann zurück zum TV-Bild geschaltet werden.

### **ID 26730, DigiCorder ISIO C MS2 Aprico2, P2 : "[IP Daun] Change the menu language. The product registration does not start."**

Status : resolved 2.57.0.1-2595d, Reproducibility : always

Change the menu language. The product registration does not start.

### **ID 27193, DigiCorder ISIO C MS2 Aprico2, P2 : "Hinweis auf HD-Plus"**

Status : resolved 2.57.0.1-2595d, Reproducibility : always

Der Hinweis auf eine Seite [www.hd-plus.de](http://www.hd-plus.de) macht in der Schweiz oder in Österreich keinen Sinn. Dieser Hinweis sollte verallgemeinert werden, oder ganz entfernt werden

**ID 27188, DigiCorder ISIO C MS2 Aprico2, P1 : ""Perfect" Recording nimmt Sendung nicht auf"**

Status : resolved 2.57.0.1-2595d, Reproducibility : several times

"Perfect" Recording ist aktiviert und es ist eine Aufnahmebereitschaft von 30 Minuten eingestellt. Es werden nun auf einem ÖR Sender 2 aufeinanderfolgende Events als Timer Aufnahmen programmiert.

Der erste Event wird vollständig aufgenommen, der zweite direkt anschließende Event wird jedoch nur als Datei angelegt, deren Aufnahmedauer lediglich 1-2 Sekunden beträgt.

Auch ein drittes Event wurde mit 2 Sekunden aufgenommen.

#0027179

**ID 27211, DigiCorder ISIO C MS2 Aprico2, P2 : "Continuous PIN dialog when starting any DVR playback on live channel with PIN protected event"**

Status : resolved 2.57.0.1-2595d, Reproducibility : always

- Switch to channel with FSK event which could be descrambled by side of a CI module ( and therefore would lead to user PIN request dialog )
- Start any DVR playback ( NAV -> Own Records ) in fullscreen mode
- The PIN request dialog (from previous live service) is continuously shown

**ID 27236, DigiCorder ISIO C MS2 Aprico2, P- : "keine Wiedergabe vom Maxdome Kauf-oder Leihfilm"**

Status : resolved 2.57.0.1-2595d, Reproducibility : several times

Zeitweise ist keine Wiedergabe von Maxdome Kauf-oder Leihfilmen möglich. Der Bandbreitencheck ist erfolgreich, der Film versucht dann auch mehrfach zu starten. Während diesen Versuchen wird das Maxdome Bedienfeld mit Fortschrittsbalken immer wieder ein-bzw. ausgeblendet. Nach 3 Versuchen erscheint die Meldung "Seite nicht verfügbar" (siehe Screenshot, siehe Video). Die Wiedergabe von Trailern funktioniert hingegen ohne Probleme.

Nach einer Netztrennung des Gerätes oder nach der Trennung des LAN-Kabels laufen diese Filme wieder.

Fehler konnte mehrfach an meinem Testbox beobachtet werden und es liegen gleichlautende Kundenreklamationen im Service Center vor.

**ID 26440, DigiCorder ISIO C MS2 Aprico2, P2 : "Broadcast info (SI) at Kabel Kiosk channels -> Special characters faulty."**

Status : closed 2.57.0.1-2595c, Reproducibility : always

Broadcast info (SI) at Kabel Kiosk channels -> Special characters faulty.

**ID 26926, DigiCorder ISIO C MS2 Aprico2, P1 : "[KabelKiosk]: If there is an active recording in background, all parental rated services are unblocked"**

Status : resolved 2.57.0.1-2595c, Reproducibility : always

[KabelKiosk]: If there is an active recording in background, all parental rated services are unblocked

**ID 27200, DigiCorder ISIO C MS2 Aprico2, P2 : "Empty message box when using TechniCrypt module with non paired smartcard"**

Status : resolved 2.57.0.1-2595c, Reproducibility : always

Reported by T.Proksch ( mail from 2013-10-12 )

"Wird eine STB in Verwendung mit einem TechniCrypt genutzt, in welcher eine nicht mit diesem Modul gepairte SMC eingesteckt ist, dann ist die Meldung "Kein Zugriff 8" nur ganz kurz zusehen bevor diese mit folgender Meldung überblendet wird"

**ID 25581, DigiCorder ISIO C MS2 Aprico2, P2 : "Missing translation"**

Status : closed 2.57.0.1-2595b, Reproducibility : always

Start direct recording with the REC button. Now press the REC button again. A dialogue with several options for the recording end time is shown but it is only partly translated.

"(to xx:xx)" should be for e.g. in german "(bis xx:xx)"

**ID 26718, DigiCorder ISIO C MS2 Aprico2, P2 : "Kabel Kiosk channel. The message "Kein zugriff(8) is displayed bevor the TV picture shown."**

Status : closed 2.57.0.1-2595b, Reproducibility : often

Smart cards for Kabel Kiosk and MTV are inserted in embedded slot. in Switch to Kabel kiosk channel. The message "Kein zugriff(8) is displayed bevor the TV picture shown.

**ID 26754, DigiCorder ISIO C MS2 Aprico2, P1 : "HD+ card with CI+ module: Error message while zapping between HD+ channels"**

Status : closed 2.57.0.1-2595b, Reproducibility : often

HD+ card with CI+ module: Error message while zapping between HD+ channels, "Kein Zugriff - Hinweis 8". #0026350

**ID 26845, DigiCorder ISIO C MS2 Aprico2, P2 : "[Haehnlein SW] Upnp server should allow access onto the meta file for a dvr recording"**

Status : resolved 2.57.0.1-2595b, Reproducibility : always

- Request by side of Haehnlein SW

- Upnp server should allow access onto the meta file for a dvr recording

**ID 22481, DigiCorder ISIO C MS2 Aprico2, P2 : "Not enough free space on internal storage"**

Status : closed 2.57.0.1-2595, Reproducibility : always

Enter the music organiser and select a folder (music with 29 folder and 1066 files) from an external USB HDD. Try to copy this folder. After some time a message appears:

"Not enough free space on internal storage".

Copy will not be done.

**ID 25092, DigiCorder ISIO C MS2 Aprico2, P2 : "Defective PIN query"**

Status : resolved 2.57.0.1-2595, Reproducibility : always

Slot 1: Cablevista SC

Slot 2: Kabelkiosk SC Family XL HD

Both cards are inserted-> select a channel with maturity rating-> the pin query appears and disappears constantly, every second. Therefore is a correct PIN entry not possible.

The bug does not occur if the card is not inserted in slot 1.

Customer complaint (22.04.2013, Olaf Theissig, Frankfurt a.M.)

**ID 25567, DigiCorder ISIO C MS2 Aprico2, P2 : "Non-informative release notes"**

Status : closed 2.57.0.1-2595, Reproducibility : always

After update the STB does show up only non-informative release notes ("Allgemeine Verbesserungen").

**ID 25616, DigiCorder ISIO C MS2 Aprico2, P2 : "Crash after closing release notes"**

Status : closed 2.57.0.1-2595, Reproducibility : once

The STB was update via LAN internet connection (hook was active). After successful update the release note page was shown. Now several buttons like MENU, TV/RADIO etc. were pressed before OK was pressed to leave the menu but instead of leaving the menu the STB did crash without reboot showing the "Bitte warten..." banner. After manual reset the STB did restart showing the release note page again.

**ID 25621, DigiCorder ISIO C MS2 Aprico2, P2 : "STB started in AutoInstall"**

Status : closed 2.57.0.1-2595, Reproducibility : once

There had been several OTA update tests via internet. After the last test a factory reset has been done and the AutoInstall has been completely done. After the AutoInstall assistant has been finished and closed the STB had been switched into standby overnight. On the next morning the STB has been switched on and did show the AutoInstall assistant again although there had been no factory reset. Also when cancelling the AutoInstall assistant the STB did show the last favorite list with all found services so the AutoInstall was not started again due to an empty list and there could be no factory reset been since in this case the list must have been empty.

**ID 26420, DigiCorder ISIO C MS2 Aprico2, P1 : "The STB rebooted if the second Conax smart card is inserted."**

Status : closed 2.57.0.1-2595, Reproducibility : several times

One Conax smart card is inserted in embedded slot. The second smart card is inserted in the second embedded slot. The STB is rebooted.

**ID 26433, DigiCorder ISIO C MS2 Aprico2, P1 : "It is not possible to use the Conax smart card for MTV and Conax smart card for Kabel Kiosk at the same time."**

Status : closed 2.57.0.1-2595, Reproducibility : often

The Conax smart card for MTV and Conax smart card for Kabel Kiosk are inserted in embedded slots. A some errors occurred at the Kabel Kiosk channels.

1. It is not possible to call up the SFI mode.
2. It is no sound volumen bar displayed.
3. The PIN request is displayed but the broadcast (FSK) is decoded in background.

**ID 26434, DigiCorder ISIO C MS2 Aprico2, P1 : "No SFI download manual or overnight"**

Status : closed 2.57.0.1-2595, Reproducibility : always

No SFI download manual or overnight. The connection to Sfi.technibutler.de is OK and the arte is in the TV list. But in menu programm guide the displayed: SFI channel not present.

**ID 26442, DigiCorder ISIO C MS2 Aprico2, P1 : "No information update in system configuration after SFI download in standby"**

Status : closed 2.57.0.1-2595, Reproducibility : always

Call up menu programme guide, set the update time to other time and switch the STB in standby. After the SFI download the information about SFI updating is not changed.

**ID 26485, DigiCorder ISIO C MS2 Aprico2, P1 : "Kein Live Streaming von Pay TV Sender"**

Status : closed 2.57.0.1-2595, Reproducibility : always

Pay TV Sender wie Sky sind nicht mehr über das UPnP Live Streaming verfügbar.#0026477

**ID 26495, DigiCorder ISIO C MS2 Aprico2, P1 : "Crash beim Zustecken eines CI-CAM"**

Status : closed 2.57.0.1-2595, Reproducibility : always

- Irdeto CI+ CAM mit ORF-Karte einstecken und ORF-Programm entschlüsseln
- Zweites CI-CAM (z.B. Alphacrypt) in den zweiten Slot stecken und warten ... Crash ODER
- Irdeto CI+ CAM mit ORF-Karte einstecken auf z.B. ARD
- Zweites CI-CAM (z.B. Alphacrypt) in den zweiten Slot stecken und Init. abwarten
- Auf ORF-Programm umschalten .... Crash

**ID 26499, DigiCorder ISIO C MS2 Aprico2, P1 : "Geändertes PIN Handling bei Jugendschutz Aktivierung"**

Status : closed 2.57.0.1-2595, Reproducibility : always

Das PIN Handling bei der Jugendschutz Aktivierung wurde dahingehend geändert, daß es nicht mehr notwendig ist, die bereits voreingestellte Geräte PIN einzugeben. Somit es es jedermann auch ohne Kenntnis der voreingestellten Geräte PIN möglich, das Gerät zu sperren. #0026483

**ID 25267, DigiCorder ISIO C MS2 Aprico2, P2 : "Wrong display"**

Status : closed 2.57.0.1-2587, Reproducibility : always

Not occupied channels are shown in SFI List (see attached pfd)

**ID 25577, DigiCorder ISIO C MS2 Aprico2, P2 : "App bar default value should be "off""**

Status : closed 2.57.0.1-2587, Reproducibility : always

After factory reset or AutoInstall the default value for the app bar setting should be "off".

**ID 26401, DigiCorder ISIO C MS2 Aprico2, P- : "[Haenlein SW] No playback of imported recordings created by DVR Studio HD3 after copy to folder own recordings on another volume"**

Status : closed 2.57.0.1-2587, Reproducibility : always

- Import a recording which was created with Haenlein DVR Studio HD3 to folder own recordings- Imported recording could be played back- Copy this recording to folder own recordings on another volume- After copy finished try to playback the copied record- It is not possible

**ID 22079, DigiCorder ISIO C MS2 Aprico2, P2 : "[HbbTV] Kabelkiosk choice: App is not closed after switching to another channel from inside the app"**

Status : closed 2.57.0.1-2574, Reproducibility : often

Tune to Kabelkiosk Infokanal. (Parameters in the internal cable network: 490,04 MHz, 6900 kBd, QAM256, not inverted)

Kabelkiosk offers an HbbTV autostart app 'choice'. It is possible to switch to a program on another channel from inside the app.

The app is often not closed after switching to a program on RTL, VOX, Sat.1, PRO7, or Kabel1 from the Eutelsat Kabelkiosk offer.

The app is closed when switching to a different commercial channel. (Public channels are not supported.)

Reproduce:

- open Kabelkiosk's HbbTV autostart app 'choice' by pressing the red button.  
- select 'mein Fernsehen' -> 'Jetzt im TV' -> choose a program from RTL,VOX,Sat.1,PRO7,Kabel1 -> Details -> Umschalten

This app shall always be closed after switching.

This app is NOT signalled in the AITs on RTL,VOX,Sat.1,PRO7,Kabel1.

**ID 22417, DigiCorder ISIO C MS2 Aprico2, P2 : "arte HD HBBTV no video playback"**

Status : closed 2.57.0.1-2574, Reproducibility : always

Switch to "arte HD" and open the HBBTV content with the RED button. Choose the page "ARTE +7" with the YELLOW button and select a video for e.g. "WILDE TIERE, GROÙE LIEBE". Video playback will not start and audio playback is very choppy or also not available.

**ID 22428, DigiCorder ISIO C MS2 Aprico2, P2 : "Cursor is not at correct channel with should be sort"**

Status : closed 2.57.0.1-2574, Reproducibility : always

Open "Internet lists organiser". Choose "Internet list" and mark last 2 or more channels. Remove the marked channels. Open "Options" and choose "Sort". Cursor is not at correct channel with should be sort.

**ID 25200, DigiCorder ISIO C MS2 Aprico2, P2 : "No video playback at arte mediathek"**

Status : closed 2.57.0.1-2574, Reproducibility : always

No video playback at arte mediathek

**ID 25444, DigiCorder ISIO C MS2 Aprico2, P2 : "UPnP server: own recordings with incomplete names"**

Status : closed 2.57.0.1-2574, Reproducibility : always

UPnP server is enabled and the own recordings will be provided but some recordings whose name starts with a number will appear incomplete (without the number) on UPnP clients.

Example:

21 Jump Street -> Jump Street

10.000 B.C. -> .000 B.C.

Also reproducibe with recordings that were renamed by the user.

**ID 25573, DigiCorder ISIO C MS2 Aprico2, P2 : "Software check does never finish"**

Status : closed 2.57.0.1-2574, Reproducibility : always

A STB has software version 2.56.0.2(2465b). Cable signal and network are not available. On an USB stick is software version 2.56.0.2(2465c) and a software check is triggered in menu "Software aktualisieren". The check will halt at 0%, 15% or 25% and never finish.

**ID 25578, DigiCorder ISIO C MS2 Aprico2, P2 : "STB LAN name not changed after manual restart"**

Status : closed 2.57.0.1-2574, Reproducibility : always

Enable quickstart. Open LAN menu and change the STB name ("Freigabename"). A dialogue banner will be shown informing that the STB needs to be restarted. Select "NO" from dialogue. Now leave menu and restart STB manually by switching into standby and on again. LAN name will now not change with this manual restart of the STB.

**ID 25579, DigiCorder ISIO C MS2 Aprico2, P2 : "UPnP live streaming no info on CONAX scrambled services"**

Status : closed 2.57.0.1-2574, Reproducibility : always

Enable and start UPnP live streaming of a CONAX scrambled service which can be decoded via internally used smartcard. UPnP live streaming will be blocked in UPnP client but there is no info about this.

**ID 25580, DigiCorder ISIO C MS2 Aprico2, P2 : "Empty display"**

Status : closed 2.57.0.1-2574, Reproducibility : always

Switch to a CONAX scrambled services and wait for the playback start. Now remove smartcard from internal reader. A message banner "Keine Karte eingesteckt" is shown but front display is empty not showing the error message nor the actual service name.

**ID 25588, DigiCorder ISIO C MS2 Aprico2, P2 : "Drive actualization breaks actual selection and playback"**

Status : resolved 2.57.0.1-2574, Reproducibility : often

There are several drives attached (USB, eSATA, SDcard). When opening for e.g. the movie navigator or the movie organizer the drives are enumerated and content of the actual drive is loaded. When now the navigator/organizer is switched to a drive which is not recording media (for e.g. the SDcard) the new content is listed. After a while or during (movie) playback on this drive there is a drive actualization in the background which will break all playback and does set the actual drive selection back to the recording media without any user interaction.

**ID 25589, DigiCorder ISIO C MS2 Aprico2, P2 : "File copy possible without warning although not enough disk space"**

Status : closed 2.57.0.1-2574, Reproducibility : always

Internal harddisk has only 30GB of free disk space. Now a copy of a 33.5GB movie file from an external USB drive is started. Although there is not enough disk space free the copy action is started without a warning.

**ID 25591, DigiCorder ISIO C MS2 Aprico2, P2 : "Internal harddisk found twice"**

Status : closed 2.57.0.1-2574, Reproducibility : once

The internal harddisk has been found twice after a filesystem check.

**ID 25612, DigiCorder ISIO C MS2 Aprico2, P2 : "Wrong preview scaling"**

Status : closed 2.57.0.1-2574, Reproducibility : once

The STB was programmed with a DVR timer overnight. On the next morning the STB was switched on showing the notification for the new made recording but the background preview was not correctly scaled to fullscreen.

**ID 25620, DigiCorder ISIO C MS2 Aprico2, P2 : "Crash in AutoInstall during network check"**

Status : closed 2.57.0.1-2574, Reproducibility : several times

Configure in AutoInstall a network connection via WLAN. After leaving the WLAN menu the AutoInstall setup will check the network configuration. Sometimes the STB will crash during the check and reboot.



**ID 25630, DigiCorder ISIO C MS2 Aprico2, P2 : "Radio background vanishes for some seconds"**

Status : closed 2.57.0.1-2574, Reproducibility : always

The internal HDD is powered down. Switch to radio mode and start a direct recording. The internal HDD will power up and recording will start with a small delay but the background picture will be faded out and instead a black screen is shown for several seconds until the background picture is faded in again.

**ID 25631, DigiCorder ISIO C MS2 Aprico2, P2 : "No CRM details in DVR recording longinfo"**

Status : closed 2.57.0.1-2574, Reproducibility : always

Create a recording with CRM restriction for e.g. on a KabelKiosk service. Open DVR navigator and set cursor on this recording. On the right side the small recording info does show the global CRM icon but in longinfo on the left side which can be opened with the INFO button there are no details about the active CRM restrictions (for e.g. 90min timeshift, spooling restrictions etc.).

**Already released versions:**

Release	Build number	Date of SW	Comment
---------	--------------	------------	---------